

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/10/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155236	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING _____		(X3) DATE SURVEY COMPLETED R 03/07/2014
NAME OF PROVIDER OR SUPPLIER AVON HEALTH & REHABILITATION CTR			STREET ADDRESS, CITY, STATE, ZIP CODE 4171 FOREST POINTE CIR AVON, IN 46123		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 000}	<p>INITIAL COMMENTS</p> <p>Based on a Fire Safety Evaluation System (FSES) and an acceptable plan of correction, paper compliance to the Life Safety Code Recertification and State Licensure Survey conducted on 01/02/14 was completed on 03/07/14.</p> <p>Review Date: 03/07/14</p> <p>Facility Number: 000141 Provider Number: 155236 AIM Number: 100283860</p> <p>Surveyor: Dennis Austill, Life Safety Code Supervisor</p> <p>Based on this FSES and an acceptable plan of correction, Avon Health & Rehabilitation Center was found in compliance with National Fire Protection Association (NFPA) 101A, Chapter 4, Fire Safety Evaluation System for Health Care Occupancies in regard to the Life Safety Code Recertification and State Licensure Survey. Achieving a passing score on the FSES survey for Health care Occupancies found in Chapter 4 of NFPA 101A, Alternative Approaches to Life Safety, 2001 Edition shows the facility provides a level of Life Safety at least equivalent to that prescribed by NFPA 101, LSC and 410 IAC 16.2.</p> <p>This one story facility was determined to be of Type V (111) construction and fully sprinklered. The facility has a fire alarm system with smoke detection in the corridors and in all areas open to the corridor. The facility has smoke detectors hard wired to the fire alarm system in all resident sleeping rooms.</p>	{K 000}			

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

Any deficiency statement ending with an asterisk (*) denotes a deficiency which the institution may be excused from correcting providing it is determined that other safeguards provide sufficient protection to the patients. (See instructions.) Except for nursing homes, the findings stated above are disclosable 90 days following the date of survey whether or not a plan of correction is provided. For nursing homes, the above findings and plans of correction are disclosable 14 days following the date these documents are made available to the facility. If deficiencies are cited, an approved plan of correction is requisite to continued program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/10/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155236	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING _____		(X3) DATE SURVEY COMPLETED R 03/07/2014
NAME OF PROVIDER OR SUPPLIER AVON HEALTH & REHABILITATION CTR			STREET ADDRESS, CITY, STATE, ZIP CODE 4171 FOREST POINTE CIR AVON, IN 46123		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 039} SS=E	<p>NFPA 101 LIFE SAFETY CODE STANDARD</p> <p>Width of aisles or corridors (clear and unobstructed) serving as exit access in hospitals and nursing homes is at least 8 feet. In limited care facilities and psychiatric hospitals, width of aisles or corridors is at least 6 feet. 18.2.3.3, 18.2.3.4</p> <p>This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure 2 of 8 exit access corridors had a clear and unobstructed exit width of at least 8 feet (96 inches). This deficient practice could affect 28 residents, staff and visitors if needing to exit the facility from the 800 and 900 Hall in the event of an emergency.</p> <p>Findings include:</p> <p>Based on observations with the Maintenance Director during a tour of the facility from 11:40 a.m. to 2:05 p.m. on 01/02/14, the 800 Hall and 900 Hall corridors each measured 85 inches in width. Based on interview at the time of the observations, the Maintenance Director stated the 800 Hall and 900 Hall corridors were constructed at the width of 85 inches and acknowledged the 800 Hall and 900 Hall corridors each do not have a clear and unobstructed width of at least 8 feet (96 inches).</p>	{K 039}			
{K 040} SS=E	<p>3.1-19(b)</p> <p>NFPA 101 LIFE SAFETY CODE STANDARD</p> <p>Exit access doors and exit doors used by health</p>	{K 040}			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/10/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155236	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING _____		(X3) DATE SURVEY COMPLETED R 03/07/2014
NAME OF PROVIDER OR SUPPLIER AVON HEALTH & REHABILITATION CTR			STREET ADDRESS, CITY, STATE, ZIP CODE 4171 FOREST POINTE CIR AVON, IN 46123		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 040}	<p>Continued From page 2</p> <p>care occupants are of the swinging type with openings of at least 41.5 inches wide. Doors in exit stairway enclosures are no less than 32 inches in clear width. In ICFs/MR, doors are at least 32 inches wide. 18.2.3.5</p> <p>This STANDARD is not met as evidenced by: Based on observation and interview, the facility failed to ensure 2 of 5 exit doors in the means of egress from the corridors in the 800 and 900 Hall had a minimum clear width of 41.5 inches, and 26 of 26 resident room exit doors in the 800 Hall and 900 Hall had a minimum clear width of 41.5 inches. This deficient practice could affect 28 residents, staff and visitors needing to exit any resident room in the 800 Hall and 900 Hall.</p> <p>Findings include:</p> <p>Based on observations with the Maintenance Director during a tour of the facility from 11:40 a.m. to 2:05 p.m. on 01/02/14;</p> <p>a. the north exit door in the means of egress from the 800 Hall and the south exit door in the means of egress from the 900 Hall each measured 36 inches in width.</p> <p>b. all resident room exit doors in the 800 Hall and 900 Hall measured 36 inches in width.</p> <p>Based on interview at the time of the observations, the Maintenance Director acknowledged the north and south exit doors in the means of egress from the 800 Hall and 900 Hall and each resident room exit door in the 800 Hall and 900 Hall measured 36 inches in width.</p>	{K 040}			

DEPARTMENT OF HEALTH AND HUMAN SERVICES
CENTERS FOR MEDICARE & MEDICAID SERVICES

PRINTED: 03/10/2014
FORM APPROVED
OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: 155236	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING _____		(X3) DATE SURVEY COMPLETED R 03/07/2014
NAME OF PROVIDER OR SUPPLIER AVON HEALTH & REHABILITATION CTR			STREET ADDRESS, CITY, STATE, ZIP CODE 4171 FOREST POINTE CIR AVON, IN 46123		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETION DATE	
{K 040}	Continued From page 3 3.1-19(b)	{K 040}			